

# BIBS CERTIFICATE

Certificate no: DSC-2026-000622

Service date: 08.04.2026

Valid until: 08.04.2027

Result: **Fail**

## Equipment details

Customer: Valen marina AS  
Producer: Scott  
Serial no: Intern 006  
Service interval: 12 months

Location: Chamber Container  
Model: Pressur Vak  
Build year: -

## OVERVIEW

General condition	Fail
Mask	Fail
Coupling nipple O-ring	Fail
Head strap	Fail

## INHALATION VALVE (O<sub>2</sub>)

O <sub>2</sub> membrane	Fail
O-ring membrane housing O <sub>2</sub>	Fail
Swivel nipple O <sub>2</sub>	Fail
O-ring O <sub>2</sub>	Fail
O <sub>2</sub> hose	Fail

## EXHALATION VALVE (EXHAUST)

Exhaust membrane	Fail
O-ring membrane housing exhaust	Fail
Swivel nipple exhaust	Fail
O-rings	Fail
Exhaust hose	Fail
Cleaned	Fail

## Technician

Notes: Broken mask and housing, not repairable

Serviced by: Daniel Kristensen

Signature

*Daniel Kristensen*

