

HYPERBARIC CHAMBER SERVICE CERTIFICATE

DSC-2026-000651

Service date: 13.04.2026

Valid to: 13.04.2027

Result: **Approved**

Equipment details

Customer: Kystarbeid AS
Producer: Imenco
Serial no: 1385
Service interval: 12 months

Location: Chamber Container
Model: Chamber 1800MM
Build year: 2010

Pressure

Pressure reducing valve	15.0	Pass
Main chamber overpressure valve Recommend install valve to emergency close	6.3	Pass
Entry lock overpressure valve	—	-
Pipe maximum working pressure	200.0	Pass

Pressure test

Pressure: — bar
Time: — min
Descent: — min
Ascent: — min

Hydro

Last hydrostatic test:
01.06.2022
Next hydrostatic test:
01.06.2032
Hydrotested: No
Testrange: —

Checklist

General condition	Pass	Communication – main chamber	Pass
Entry lock inlet valve	Pass	Communication – Entry lock	Pass
Entry lock outlet valve	Pass	Gasket – medical lock	Pass
Main chamber inlet valve	Pass	Gasket – Entry lock door	Pass
Main chamber outlet valve	Pass	Gasket – main chamber door	Pass
Depth alarm – audible signal	Pass	Window/viewport	Pass
Depth gauge see calibration certificate	Pass	Valves & Piping	Pass
High pressure gauge (HP)	Pass	Lightening	Pass
Low pressure gauge (LP)	Pass	Cameras	Pass
BIBS / O ₂ mask see bibs certificate, Recommend to install valves inlet and outlet on block	Pass	Surface treatment inside/outside	Pass
LP bank	-	Equalizer	Pass
HP Bank 3x80L 300bar, New 2024	Pass	Drainage	Pass
O ₂ needle valves internal / external	Pass		

Technician

Serviced by: Daniel Kristensen

Signature

