

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000409

Service date: 22.02.2026

Valid until: 22.02.2027

Result: **Approved**

Equipment details

Customer: Sjøentreprenøren AS
Producer: Faber
Serial no: 15/1912/086
Service interval: 24 months

Location: Mjø
Model: Diving cylinder
Build year: 2015

Data

Cylinder type: Steel Color: Yellow Cylinder volume: 10.0
Oxygen cleaned: No Working pressure (bar): 300 Test pressure (bar): 490 Application type: Diving
Test facility number: D79 Weight (kg): 15.00 Thread type: M25x2 Hydro tested: 02/2026

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Value: 5.9	
		Exterior approved	-

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Value: 0	
Sealing surface damaged	Pass	Interior approved	Pass

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	-	Filling connection thread	Pass
Valve/cylinder thread	Pass		



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000409

Service date: 22.02.2026

Valid until: 22.02.2027

Result: **Approved**

General

Repairs on cylinder

No

Cylinder and valve approved

Pass

Technician

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

