

# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000599

Service date: 06.04.2026

Valid until: 06.03.2035

Result: **Approved**

## Equipment details

Customer: Sjøentreprenøren AS  
Producer: SEFIC  
Serial no: 25AG062 021UT  
Service interval: 24 months

Location: Alu kontainer  
Model: 5L cylinder  
Build year: 2025

## Data

Cylinder type: Oxygen Steel      Color: white      Cylinder volume: 5.0  
Oxygen cleaned: Yes      Working pressure (bar): 230      Test pressure (bar): 345      Application type: Surface  
Test facility number: -      Weight (kg): 7.40      Thread type: 25E      Hydro tested: 03/2025

## Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Value: 3.5	
		Exterior approved	Pass

## Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Value: 0	
Sealing surface damaged	Pass	Interior approved	Pass

## Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

## Valve

Overhauled	-	Filling connection thread	Pass
Valve/cylinder thread	Pass		



# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000599

Service date: 06.04.2026

Valid until: 06.03.2035

Result: **Approved**

## General

Repairs on cylinder

- Cylinder and valve approved

Pass

## Technician

Notes: New Oxygen cylinder 5L, Only VP and Oxygen cleaning

Serviced by: Daniel Kristensen

Signature

*Daniel Kristensen*

