

1.STAGE BAILOUT

Certificate no: DSC-2026-000577

Service date: 11.12.2025

Valid until: 11.12.2026

Result: **Approved**

Equipment details

Customer: Samba Marin AS
Producer: Poseidon
Serial no: 2312056
Service interval: 12 months

Location: Fox Inspector
Model: Cyklon
Build year: -

NOTE

Tested with Labtec PRO

This is a certificate confirmation, the documentation has a separate file.

Technician

Serviced by: Daniel Kristensen

Signature



workshop: DS BERGEN AS		person:	Daniel Kristensen
street: Storebotn 55G		phone:	91649162
place: 5309 Klepppestø		fax:	
		email:	Daniel@dsbergen.no
customer: Samba Marin		person:	An-Magridd
street: Røtingavegen 4		phone:	91841270
place: 5216 Søre Øyane		fax:	
		email:	Foxinspector@sambamarin.no
device data:	deadlines:	device-info:	service:
device no: 2312056	1 y test 11.12.2026		- 1 year service
	1 y srv 11.12.2026		- 10 year service
	10 y srv 11.12.2035		- 15 year service
	15 y srv 11.12.2040		- cleaning and disinfection
type: Poseidon Cyklon			
class: diving system basic			
location: Fox inspector			

New bailout 1.stage without gauge and hoses.

tests/measurements	unit	min	max	actual	result
visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...)			0	0	OK
HP leakage at max pressure after 0,5 min	bar	-5		-1	OK
demand valve opening pressure	bar	12	21	18	OK
static medium pressure at 150 bar cylinder pressure	bar	8	10,5	10,1	OK
MP leakage after 0,5 min at 190 bar lmt. 1 0=rel.1=abs. pulse	bar		10,5	10,2	OK
pressure comparison at 190 bar	bar	-10	10	0	OK
pressure comparison at 60 bar	bar	-10	10	0	OK
pressure release of test equipment (HP, MP and LP)				0	OK

test executed: 11.12.2025 14:40
 by: Daniel Kristensen

result:

test signed: 11.12.2025 14:40
 by: Daniel Kristensen

device ready for use

Lab.Net Profi V: 2024.0.0.0

next test on: 11.12.2026