

# BAILOUT 1.STAGE

Certificate no: DSC-2026-000579

Service date: 26.08.2025

Valid until: 26.08.2026

Result: **Approved**

## Equipment details

Customer: Samba Marin AS  
Producer: Scubapro  
Serial no: 1844500744  
Service interval: 12 months

Location: Fox Inspector  
Model: MK17  
Build year: 2018

## NOTE

Tested with Labtec PRO

This is a certificate confirmation, the documentation has a separate file.

## Technician

Serviced by: Daniel Kristensen

Signature



<b>workshop:</b> DS BERGEN AS		person:	Daniel Kristensen
street: Storebotn 55G		phone:	91649162
place: 5309 Kleppestø		fax:	
		email:	Daniel@dsbergen.no
<b>customer:</b> Samba Marin		person:	An-Magridd
street: Røtingavegen 4		phone:	91841270
place: 5216 Søre Øyane		fax:	
		email:	Foxinspector@sambamarin.no
<b>device data:</b>	<b>deadlines:</b>	<b>device-info:</b>	<b>service:</b>
device no: 1844500744	1 y test 26.08.2026 1 y srv 26.08.2026		- 1 year service - cleaning and disinfection
type: Scubapro MK17			
class: diving system basic			
location: Fox inspector			

Bailout reg set, New hoses and Gauge, New OPV

tests/measurements	unit	min	max	actual	result
visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...)			0	0	OK
HP leakage at max pressure after 0,5 min	bar	-5		0	OK
demand valve opening pressure	bar	12	21	16,6	OK
static medium pressure at 200 bar cylinder pressure	bar	8	10,5	9,4	OK
MP leakage after 0,5 min at 200 bar lmt. 1 0=rel.1=abs. pulse	bar		10,5	9,5	OK
pressure comparison at 200 bar	bar	-10	10	1	OK
pressure comparison at 60 bar	bar	-10	10	-2	OK
pressure release of test equipment (HP, MP and LP)				0	OK

test executed: 26.08.2025 16:20  
 by: Daniel Kristensen

result:

test signed: 26.08.2025 16:22  
 by: Daniel Kristensen

device ready for use

Lab.Net Profi V: 2024.0.0.0

next test on: 26.08.2026