

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000363

Service date: 18.02.2026

Valid until: 18.02.2028

Result: **Approved**

Equipment details

Customer: Otech AS
Producer: ECS
Serial no: LNI101UT
Service interval: 24 months

Location: CCB
Model: Cylinder
Build year: 2022

Data

Cylinder type: Steel Color: white Cylinder volume: 12.0
Oxygen cleaned: - Working pressure (bar): 300 Test pressure (bar): 450 Application type: Diving
Test facility number: D79 Weight (kg): 18.00 Thread type: M25x2 Hydro tested: -

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Comment: some corrosion	
Odor	Pass	Exterior condition	Pass
Dent or bulge	Pass	Minimum wall thickness	Pass
		Value: 5,1	
		Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Value: 0	
Sealing surface damaged	Pass	Interior approved	Pass

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Value: 0,00	
		Pressure testing approved	Pass

Valve

Overhauled	Yes	Filling connection thread	Pass
------------	-----	---------------------------	------



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000363

Service date: 18.02.2026

Valid until: 18.02.2028

Result: **Approved**

Valve/cylinder thread

Pass

Value: G5/8

General

Repairs on cylinder

No

Cylinder and valve approved

Pass

Technician

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

