

# 1.STAGE BAILOUT

Certificate no: DSC-2026-000543

Service date: 11.03.2026

Valid until: 11.03.2027

Result: **Approved**

## Equipment details

Customer: Techno Dive AS  
Producer: Poseidon  
Serial no: P500551  
Service interval: 12 months

Location: Katrine  
Model: Cyklon  
Build year: -

## NOTE

Tested with Labtec

This is a certificate confirmation, the documentation has a separate file.

## Technician

Serviced by: Daniel Kristensen

Signature

*Daniel Kristensen*



## test report

test report: 440  
 device no.: P500551  
 type of Yearly test  
 test system: PRO 3102.24.325

|                                 |   |                     |   |
|---------------------------------|---|---------------------|---|
| <b>workshop:</b> DS BERGEN AS   |   | person:             | Daniel Kristensen                               |
| street: Storebotn 55G           |   | phone:              | 91649162  |
| place: 5309 Kleppestø           |   | fax:                |   |
|                                 |   | email:              | Daniel@dsbergen.no                              |
| <b>customer:</b> Techno Dive AS |   | person:             | Thor Erik Madsen                                |
| street: Husøyvegen 153          |   | phone:              |   |
| place: 4262 Avaldsnes           |   | fax:                |   |
|                                 |   | email:              | tem@techno-dive.no                              |
| <b>device data:</b>             | <b>deadlines:</b>                         | <b>device-info:</b> | <b>service:</b>                                 |
| device no: P500551              | 1 y test 11.03.2027<br>1 y srv 11.03.2027 |                     | - 1 year service<br>- cleaning and disinfection |
| type: Poseidon Cyklon           |   |                     |   |
| class: diving system basic      |   |                     |   |
| location:                       |   |                     |   |

1.trinn bailout m/manometer.  
 Nytt manometer

| tests/measurements   | unit | min | max  | actual | result |
|--|------|-----|------|--------|--------|
| visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...) |      |     | 0    | 0      | OK     |
| High-pressure leak test, test time: 0,5 min, test pressure: bar        | bar  | -5  |      | -3     | OK     |
| safety valve opening pressure  | bar  | 12  | 21   | 13,4   | OK     |
| static medium pressure at 150 bar cylinder pressure                    | bar  | 8   | 10,5 | 9,6    | OK     |
| MP leakage after 0,5 min at 190 bar lmt. 1<br>0=rel.1=abs. pulse       | bar  |     | 10,5 | 9,3    | OK     |
| pressure comparison at 190 bar   | bar  | -10 | 10   | -2     | OK     |
| pressure comparison at 60 bar  | bar  | -10 | 10   | -3     | OK     |
| pressure release of test equipment (HP, MP and LP)                     |      |     |      | 0      | OK     |

test executed: 11.03.2026 23:45  
 by: Daniel Kristensen  
 test signed: 11.03.2026 23:45  
 by: Daniel Kristensen

**result:**  
**device ready for use**

LabNet V: 2025.12.2.0

next test on: 11.03.2027