

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000609

Service date: 06.04.2026

Valid until: 06.04.2031

Result: **Approved**

Equipment details

Customer: Sjøentreprenøren AS
Producer: n/a
Serial no: 5496362
Service interval: 60 months

Location: Alu kontainer
Model: Cylinder
Build year: 1982

Data

Cylinder type: Steel Color: Black Cylinder volume: 50.0
Oxygen cleaned: No Working pressure (bar): 200 Test pressure (bar): 300 Application type: Surface
Test facility number: Å79 Weight (kg): - Thread type: 25E Hydro tested: 04/2026

Exterior

Heat damage	Pass	Weight	Pass
Repainted	Yes	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Comment: Noe invendig rust	
Sealing surface damaged	Pass	Interior approved	Pass

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	Yes	Filling connection thread	Pass
Comment: Byttet kran			
Valve/cylinder thread	Pass		



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000609

Service date: 06.04.2026

Valid until: 06.04.2031

Result: **Approved**

General

Repairs on cylinder

Yes Cylinder and valve approved

Pass

Comment: Byttet kran

Technician

Serviced by: Daniel Kristensen

Signature

