

# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000609

Service date: 06.04.2026

Valid until: 06.04.2031

Result: **Approved**

## Equipment details

Customer: Sjøentreprenøren AS  
Producer: n/a  
Serial no: 5496362  
Service interval: 60 months

Location: Alu kontainer  
Model: Cylinder  
Build year: 1982

## Data

Cylinder type: Steel                      Color: Black                      Cylinder volume: 50.0  
Oxygen cleaned: No                      Working pressure (bar): 200                      Test pressure (bar): 300                      Application type: Surface  
Test facility number: Å79                      Weight (kg): -                      Thread type: 25E                      Hydro tested: 04/2026

## Exterior

Heat damage	Pass	Weight	Pass
Repainted	Yes	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

## Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Comment: Noe invendig rust	
Sealing surface damaged	Pass	Interior approved	Pass

## Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

## Valve

Overhauled	Yes	Filling connection thread	Pass
Comment: Byttet kran			
Valve/cylinder thread	Pass		



# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000609

Service date: 06.04.2026

Valid until: 06.04.2031

Result: **Approved**

## General

Repairs on cylinder

Yes    Cylinder and valve approved

Pass

Comment: Byttet kran

## Technician

Serviced by: Daniel Kristensen

Signature

