

CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000634

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

Equipment details

Customer: Valen marina AS
Producer: Carbotainer
Serial no: 072032
Service interval: 24 months

Location: Chamber Container
Model: Cylinder Composite
Build year: 2023

Data

Cylinder type: Composite Color: grey Cylinder volume: 50.0
Oxygen cleaned: - Working pressure (bar): 200 Test pressure (bar): 300 Application type: Surface
Test facility number: - Weight (kg): 23.00 Thread type: 25E Hydro tested: 02/2023

Exterior

| | | | |
|---------------|------|------------------------|------|
| Heat damage | Pass | Weight | Pass |
| Repainted | No | Line corrosion | Pass |
| Hammer test | Pass | Exterior condition | Pass |
| Odor | Pass | Minimum wall thickness | Pass |
| Dent or bulge | Pass | Exterior approved | Pass |

Interior

| | | | |
|-----------------------------------|------|--------------------------|------|
| Interpreted (thread verification) | Pass | Amount of loose material | Pass |
| Threads approved | Pass | Pitting corrosion depth | Pass |
| Crack formation | Pass | Interior approved | Pass |
| Sealing surface damaged | Pass | | |

Valve

| | | | |
|-----------------------|------|---------------------------|------|
| Overhauled | No | Filling connection thread | Pass |
| Valve/cylinder thread | Pass | | |

General

| | | | |
|---------------------|----|-----------------------------|------|
| Repairs on cylinder | No | Cylinder and valve approved | Pass |
|---------------------|----|-----------------------------|------|

Technician



CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000634

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

