

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000722

Service date: 27.05.2026

Valid until: 27.05.2028

Result: **Approved**

Equipment details

Customer: Bergen Brannvesen AS
Producer: Interspiro
Serial no: 0L4909 / 10
Service interval: 24 months

Location: Bergen Brannvesen
Model: Cylinder
Build year: 2015

Data

Cylinder type: Steel Color: white Cylinder volume: 4.0
Oxygen cleaned: No Working pressure (bar): 300 Test pressure (bar): 450 Application type: Diving
Test facility number: D79 Weight (kg): 5.60 Thread type: M18 Hydro tested: 05/2026

Exterior

| | | | |
|---------------|------|------------------------|------|
| Heat damage | Pass | Weight | Pass |
| Repainted | No | Line corrosion | Pass |
| Hammer test | Pass | Exterior condition | Pass |
| Odor | Pass | Minimum wall thickness | Pass |
| Dent or bulge | Pass | Exterior approved | Pass |

Interior

| | | | |
|-----------------------------------|------|--------------------------|------|
| Interpreted (thread verification) | Pass | Amount of loose material | Pass |
| Threads approved | Pass | Pitting corrosion depth | Pass |
| Crack formation | Pass | Interior approved | Pass |
| Sealing surface damaged | Pass | | |

Pressure testing

| | | | |
|-------------------|------|-----------------------------------|------|
| Water temperature | Pass | PU (test pressure reached) | Pass |
| Water fill (in) | Pass | PU% (percentage of test pressure) | Pass |
| Water drain (out) | Pass | Pressure testing approved | Pass |

Valve

| | | | |
|-----------------------|------|---------------------------|------|
| Overhauled | No | Filling connection thread | Pass |
| Valve/cylinder thread | Pass | | |



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000722

Service date: 27.05.2026

Valid until: 27.05.2028

Result: **Approved**

General

Repairs on cylinder

No

Cylinder and valve approved

Pass

Technician

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

