

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000771

Service date: 29.06.2026

Valid until: 01.03.2029

Result: **Approved**

Equipment details

Customer: Frøy AS
Producer: ECS
Serial no: CGF064UT
Service interval: 24 months

Location: 10Ft henger
Model: Twinset
Build year: 2026

Data

Cylinder type: Steel 2x7	Color: white	Cylinder volume: 7.0
Oxygen cleaned: -	Working pressure (bar): 300	Test pressure (bar): 450
Test facility number: -	Weight (kg): 8.70	Thread type: M25x2
		Application type: Diving
		Hydro tested: -

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	No	Filling connection thread	Pass
Valve/cylinder thread	Pass		



Certificate no: DSC-2026-000771

Valid until: 01.03.2029

Result: **Approved**

Repairs on cylinder

No

Cylinder and valve approved

Pass

Notes: New 2x7 300Bar with singel outlet bailout

Serviced by: Daniel Kristensen

Signature

Daniel K. Benson

